



INVOICE DATE 20-Jan-20	
INVOICE NO. *QUOTE*	PAGE 1
CUSTOMER NO. 00100	BRANCH

CASH CUSTOMER

SOLD TO:

SHIP TO:

CUSTOMER P.O.	REFERENCE NO.	LF 000/000
---------------	---------------	------------

	PRICE/PER	EXTENSION
R/O STATUS: Q QUOTE	PRINT JOB TOTALS: Y	
TERMS: (01) NET 30 DAYS		
EXPIRES: 04/18/2020		
UNIT: YEAR: 2010 MAKE/MODEL: PROSTAR		
SERIAL: AC168088 MILEAGE: 707132		
JOB#01 00 012 02 HOOK UP AND PERFORM DIAGNOSTICS		
4214 AFT DOC SYSTEM 4 COUNTS ACTIVE		0001
245 FAN CONTROL CIRCUIT 1 COUNT INACTIVE		0002
2375 EGR TEMP SENSOR CIRCUIT 1 COUNT INACTIVE		0003
	PARTS SUBTOTAL	0.00
* 1.00 HOURS	LABOR SUBTOTAL	115.00
	** JOB SUBTOTAL	115.00
JOB#02 00 000 12 ALL ENGINES, CAT, CUMMINS, DET, NAV, AIR TO AIR; RAD		
CUSTOMER STATES TRIANGLE LIGHT HAS BEEN ON FOR SOME TIME		0001
WILL NOT REGEN CUSTOMER STOPPED AT A T/A AND THEY		0002
PERFORMED A FORCED REGEN AND TOLD HIM IT DID NOT COME UP		0003
TO TEMP BUT REGEN WENT THROUGH AND HAD A DOC ISSUE		0004
ENFINE MAKES A WEEZING NOISE WHILE DRIVING AT HIGHWAY		0005
SPEEDS SEEMS TO BE LACKING POWER		0006
TRUCK HAS BEEN SETTING FOR AWHILE (2018)		0007
.		0008
PERFORMED T/S TESTS FOR CODE 4214 AS PER SHOP MANUAL		0009
VERIFIED NO RELATED CODES ATTEMPT A FORCED REGEN FOUND		0010
EXHAUST TEMPS WOULD ONLY GET TO 400 DEG ON THE INLET		0011
SIDE CHECKED OVER INTAKE AND EXHAUST FOUND SMALL		0012
EXHAUST LEAK AT TURBO OUTLET PIPE DUE TO BROKEN V-BAND		0013
CLAMP REMOVED PIPING FROM THE PRESSURE SIDE OF TURBO		0014
FOUND TURBO PUSHING OIL INTO PIPING HOOK UP AND SMOKE		0015
TEST CAC AND INTAKE NO LEAKS ALONG WITH EXHAUST PASS		0016

REFUND POLICY NO REFUND WITHOUT THIS INVOICE. NO PARTS RETURNABLE AFTER 10 DAYS. 15% HANDLING CHARGE ON ALL RETURNABLE PARTS. NO REFUNDS ON ELECTRICAL PARTS AND INSTALLED ITEMS.	CORE POLICY NO CREDIT WITHOUT THIS INVOICE CORES DUE WITHIN 15 DAYS OF SALE OR NO CREDIT ISSUED.
---	---

FREIGHT	SUBTOTAL	TAX STATUS/STATE	SALES TAX	PLEASE PAY
				CONTINUED

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. AND THE SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTIONS WITH THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7, AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF.

X _____
CUSTOMER SIGNATURE




INVOICE DATE 20-Jan-20	
INVOICE NO. *QUOTE*	PAGE 2
CUSTOMER NO. 00100	BRANCH

CASH CUSTOMER

SOLD TO:

SHIP TO:

CUSTOMER P.O.	REFERENCE NO.			LF	000/000
			PRICE/PER	EXTENSION	
WILL NEED TO REPLACE TURBO CHARGER ASSMY (MAY NEED ACTUATOR) REPAIR EXHAUST LEAK AT DOWN PIPE AND PERFORM A PARKED REGEN AND RETEST STILL MAY NEED TO REPLACE DOC AND DPF MAY NEED CLEANED					0017 0018 0019 0020
			PARTS SUBTOTAL	0.00	
* 3.50 HOURS			LABOR SUBTOTAL	402.50	
			SHOP SUPPLIES	40.25	
			** JOB SUBTOTAL	442.75	
JOB#03 00 000 19 STATE INSP. (ANNUAL)					
OLD MILES _____ NEW MILES _____					0001
BRAKES _____ TIRES _____					0002
LF _____ RF _____ LF _____ RF _____					0003
			LFO _____ RFO _____		0004
LR _____ RR _____ LFI _____ RFI _____					0005
			LRO _____ RRO _____		0006
TECH NAME _____ LRI _____ RRI _____					0007
					0008
NEW STICKER # & EXPIRATION _____					0009
			PARTS SUBTOTAL	0.00	
* 1.00 HOURS			LABOR SUBTOTAL	50.00	
			** JOB SUBTOTAL	50.00	
JOB#04 00 000 12 ALL ENGINES, CAT, CUMMINS, DET, NAV, AIR TO AIR; RAD					
DISASSEMBLE REMOVE AND REPLACE TURBO CHARGER ASSMY DUE TO INTERNAL FAILURE CHECK AND REPLACE TURBO ACTUATOR IF NEEDED CLEAN CAC PIPING REASSEMBLE PERFORM PARKED REGEN AND RETEST					0001 0002 0003 0004
REPLACE V-CLAMP AT TURBO DOWN PIPE DUE TO BEING BROKEN AND LEAKING EXHAUST					0005 0006
1 CU	5457297RX	TURBO	\$6435.90 EXC	4666.03EA	4666.03 1000
REFUND POLICY			CORE POLICY		
NO REFUND WITHOUT THIS INVOICE. NO PARTS RETURNABLE AFTER 10 DAYS. 15% HANDLING CHARGE ON ALL RETURNABLE PARTS. NO REFUNDS ON ELECTRICAL PARTS AND INSTALLED ITEMS.			NO CREDIT WITHOUT THIS INVOICE CORES DUE WITHIN 15 DAYS OF SALE OR NO CREDIT ISSUED.		
FREIGHT		SUBTOTAL	TAX STATUS/STATE	SALES TAX	PLEASE PAY
					CONTINUED
<small>ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. AND THE SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTIONS WITH THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7, AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF.</small>					TERMS
 CUSTOMER SIGNATURE					



INVOICE DATE 20-Jan-20	
INVOICE NO. *QUOTE*	PAGE 3
CUSTOMER NO. 00100	BRANCH

CASH CUSTOMER

SOLD TO:

SHIP TO:

CUSTOMER P.O.		REFERENCE NO.		LF 000/000			
				PRICE/PER	EXTENSION		
1 CU	5457297RX-C1	TURBO	\$1610.00 CHG	1167.25EA	1167.25	1001	
1 CU	4034289RX	KIT, VG TUR ACT	\$1915.04 EXC	1388.40EA	1388.40	1002	
1 CU	4034289RX-C1	KIT, VG TUR ACT S	\$287.50 CHG	208.44EA	208.44	1003	
1 CU	3896337	CLAMP, V BAND	\$72.78	52.77EA	52.77	1004	
1 CU	3684355	GASKET, EXH OUT CONNEC	\$20.58	14.92EA	14.92	1005	
1 IS	FLTRELC5050G	FLUID, FLEETRITE RELC	\$11.31	10.74EA	10.74	1006	
2 MI	12508	DISC, SURFACE PREP	\$4.40	2.95EA	5.90	1007	
		PARTS SUBTOTAL			7514.45		
*	6.50 HOURS	LABOR SUBTOTAL			747.50		
		SHOP SUPPLIES			74.75		
		** JOB SUBTOTAL			8336.70		
JOB#05 00 000 12 ALL ENGINES, CAT, CUMMINS, DET, NAV, AIR TO AIR; RAD							
		COOLANT LEAK AT RESERVOIR TANK				0001	
		TEST AND REPLACE TANK CAP				0002	
		REMOVE AND REPLACE COOLANT LEVEL SENSOR DUE TO LEAKING				0003	
		VACUUM FILL COOLING SYSTEM STEAM CLEAN ROAD TEST AND RECHECK				0004	
						0005	
1 IS	FLTRELC5050G	FLUID, FLEETRITE RELC	\$11.31	10.74EA	10.74	1002	
1 IH	3572012C1	SWITCH	\$121.53	99.62EA	99.62	1003	
1 IH	3578833C3	CAP	\$49.07	39.85EA	39.85	1004	
		PARTS SUBTOTAL			150.21		
*	1.00 HOURS	LABOR SUBTOTAL			115.00		
		SHOP SUPPLIES			11.50		
		** JOB SUBTOTAL			276.71		
JOB#06 00 000 07 ALL PIPES, MUFFLERS, CLAMPS, HANGERS, SHIELDS & LEAKS							
		REMOVE AND INSTALL DPF/DOC ASSMY				0001	
		DISASSEMBLE TEST AND CLEAN DPF AS NEEDED				0002	
		REPLACE DOC ASSMY				0003	
1 CU	2888263RX	MODULE, INLET CA	\$5409.52 EXC	3921.90EA	3921.90	1000	
REFUND POLICY				CORE POLICY			
NO REFUND WITHOUT THIS INVOICE. NO PARTS RETURNABLE AFTER 10 DAYS. 15% HANDLING CHARGE ON ALL RETURNABLE PARTS. NO REFUNDS ON ELECTRICAL PARTS AND INSTALLED ITEMS.				NO CREDIT WITHOUT THIS INVOICE CORES DUE WITHIN 15 DAYS OF SALE OR NO CREDIT ISSUED.			
FREIGHT		SUBTOTAL		TAX STATUS/STATE		SALES TAX	
						PLEASE PAY	
						CONTINUED	
X CUSTOMER SIGNATURE				ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. AND THE SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTIONS WITH THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7, AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF.			



INVOICE DATE 20-Jan-20	
INVOICE NO. *QUOTE*	PAGE 4
CUSTOMER NO. 00100	BRANCH

CASH CUSTOMER

SOLD TO:

SHIP TO:

CUSTOMER P.O.	REFERENCE NO.		PRICE/PER	EXTENSION	
				LF 000/000	
1 CU	2888263RX-C1	MODULE, INLET CAT \$644.00 CHG	466.90EA	466.90	1001
1 IH	3853371C1	GASKET \$27.71	22.71EA	22.71	1002
2 CU	2871453	GASKET, ADAPTER \$47.64	34.54EA	69.08	1003
1 IH	3621545C1	CLAMP \$48.01	39.35EA	39.35	1004
2 CU	2871863	CLAMP, V BAND \$119.08	86.33EA	172.66	1005
1 IH	FLTEC400TST	CLAMP, GENERAL PURPOSE \$9.63	8.50EA	8.50	1006
1 IH	3846392C1	GASKET, EXH PIPE FLANG \$19.35	15.86EA	15.86	1007
2 IH	FLTXC50GS	CLAMP \$17.19	14.61EA	29.22	1008
1 IH	3810955C1	STRAP MUFFLER SUPT \$117.64	99.69EA	99.69	1009
		PARTS SUBTOTAL		4845.87	
*	4.00 HOURS	LABOR SUBTOTAL		460.00	
		SHOP SUPPLIES		23.00	
		** JOB SUBTOTAL		5328.87	
JOB#07	00 000 38	DPF OR DOC THERMAL & SECONDARY PNEUMATIC CLEANING			
		BAKE CLEAN AND FLOW TEST DPF ASSMY			0001
		PARTS SUBTOTAL		0.00	
*	1.00 HOURS	LABOR SUBTOTAL		364.95	
		** JOB SUBTOTAL		364.95	
JOB#08	00 000 16	HVAC; CAB CONTROLS, GLASS, CAB MOUNTS, AIR FLARINGS			
		LEFT SIDE BUMPER LATCH IS BROKEN			0001
		REPLACE LATCH ASSMY			0002
2 IH	2040956C1	RIVET BLIND* 3/16 STL \$2.70	2.29EA	4.58	1000
1 IH	3674781C1	LATCH BUMPER \$141.27	118.72EA	118.72	1001
		PARTS SUBTOTAL		123.30	
*	0.50 HOURS	LABOR SUBTOTAL		57.50	
		SHOP SUPPLIES		2.88	
		** JOB SUBTOTAL		183.68	
JOB#09	00 000 12	ALL ENGINES, CAT, CUMMINS, DET, NAV, AIR TO AIR; RAD			
		REMOVE DOSER INJECTOR CHECK CLEAN AND REINSTALL			0001

REFUND POLICY NO REFUND WITHOUT THIS INVOICE. NO PARTS RETURNABLE AFTER 10 DAYS. 15% HANDLING CHARGE ON ALL RETURNABLE PARTS. NO REFUNDS ON ELECTRICAL PARTS AND INSTALLED ITEMS.		CORE POLICY NO CREDIT WITHOUT THIS INVOICE CORES DUE WITHIN 15 DAYS OF SALE OR NO CREDIT ISSUED.	
FREIGHT	SUBTOTAL	TAX STATUS/STATE	SALES TAX
			PLEASE PAY
			CONTINUED
ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. AND THE SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTIONS WITH THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7, AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF.			TERMS

X _____
CUSTOMER SIGNATURE



INVOICE DATE 20-Jan-20	
INVOICE NO. *QUOTE*	PAGE 5
CUSTOMER NO. 00100	BRANCH

CASH CUSTOMER

SOLD TO:

SHIP TO:

CUSTOMER P.O.		REFERENCE NO.		LF 000/000	
				PRICE/PER	EXTENSION
1	CU 4963857	*GASKET, INJECTOR	\$23.76	17.23EA	17.23 1000
1	CU 5292265	*INSULATOR, INJECTOR	\$5.98	4.34EA	4.34 1001
		PARTS SUBTOTAL			21.57
*	0.50 HOURS	LABOR SUBTOTAL			57.50
		SHOP SUPPLIES			5.75
		** JOB SUBTOTAL			84.82
		*TOTAL PARTS:			12655.40
		*TOTAL LABOR:			2369.95
		*TOTAL OTHER:			0.00
		*TOTAL SHOP SUPPLIES:			158.13
REFUND POLICY			CORE POLICY		
NO REFUND WITHOUT THIS INVOICE. NO PARTS RETURNABLE AFTER 10 DAYS. 15% HANDLING CHARGE ON ALL RETURNABLE PARTS. NO REFUNDS ON ELECTRICAL PARTS AND INSTALLED ITEMS.			NO CREDIT WITHOUT THIS INVOICE CORES DUE WITHIN 15 DAYS OF SALE OR NO CREDIT ISSUED.		
FREIGHT		SUBTOTAL	TAX STATUS/STATE	SALES TAX	PLEASE PAY
		15183.48	TAXABLE	911.01	16094.49
<small>ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER. IF ANY, THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND THE SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTIONS WITH THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7, AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF.</small>					<small>TERMS</small> *QUOTE ONLY*

X _____
CUSTOMER SIGNATURE