

Engine Fault Report

Engine Type	ISX 2010	Ecm Code	CL10136.40
Engine Serial Number	79599023	Software Phase	7.70.0.71
Unit Number	1017	Extraction Date	01-17-2022 03:05:26

Active Fault Codes Description	Fault Code	Count
Aftertreatment Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level	1922	2

Inactive Fault Codes Description	Fault Code	Count
Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level	2764	2
Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level	3383	1
Roll Over Protection Brake Control Active - Condition Exists	3374	1
Anti-Lock Braking (ABS) Controller - Abnormal Update Rate	3488	2
Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate	3232	34
Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate	2771	34
Aftertreatment Diesel Exhaust Fluid Controller - Abnormal Update Rate	3597	16
Aftertreatment Diesel Particulate Filter Regeneration too Frequent - Condition Exists	3375	1
Aftertreatment Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level	2639	6
Aftertreatment Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level	1921	4
Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level	1981	5